



KITS

Reparación

Bomba

Agro/Vial



<https://www.sddirecciones.com.ar>



ventas@sddirecciones.com.ar



facebook.com/sddirecciones



[@sddirecciones](https://www.instagram.com/sddirecciones)



(011)4635-0667



11-6681-2644 / 11-2175-1923 (solo Bs.As.)



INDICE

Por Marca:

 **BALDAN**  **PAG 3**



 **Commercial Hydraulics**  **PAG 4**

    **PAG 5**

 **JOHN DEERE** 

  **PAG 6**

 **MOTOCANA**  **PAG 7**

 **NEW HOLLAND AGRICULTURE** 

 **Valmet** **PAG 8**

CODIGO	DESCRIPCION	
APBA10088	REP BBA. RACINE 1.1/4 (5336.02.0023-6)	
APBA10088	REP BBA. RACINE 1.1/4 (6020.41.0152-6)	
APBA10088	REP BBA. RACINE EIXO 1.1/4 (PDC206)	

CODIGO	DESCRIPCION	
APBA15388	REP BOMBA P 315 (171340626)	

CODIGO	DESCRIPCION	
APBA10253	REP BOMBA COMERCIAL P-50 (L-32101)	

CODIGO	DESCRIPCION	
APBA19040	REP BOMBA SISTEMA HIDR. D6 (9J-0765-P)	

CODIGO	DESCRIPCION	
APBA10307	REP BBA. DIRECC (TODOS) (900803048)	

CODIGO	DESCRIPCION	
APBA10253	REP. BOMBA COM P-50 - BORR. (3.911.802.174)	
APBA 10253	REP. BOMBA COM P-50 - BORR. (1920.161.9)	
APBA 12395	REP. BBA. COML. P-30 (RET.CAU) (1920.097.3)	
APBA 15388	REP. BBA. PARKER P315 DUPLA (3.911.822.079)	
APBA 15687	REP. BOMBA P350 TRIPLA (3.911.802.016)	
APBA 15923	REP. BOMBA P365 SIMPLES (26697)	
	REP. BOMBA P365 SIMPLES (3.911.801.008)	
APBA 17072	REP. BOMBA PARKER P315 SIMPLES (3.911.802.005)	
APBA 17073	REP. BOMBA P350 DUPLA (3.911.802.012)	
APBA17074	REP. BOMBA P365 DUPLA (3.911.802.480)	
APBA 21069	REP. BBA. COML. P-330 SIMPLES-C/RET.CAUCHO	
APBA 21326	REP. BBA. COML. TRIPLA - C/RET.CAUCHO (005)	
APBA 21327	REP. BBA. COML. TRIPLA - C/RET.VITON (006)	

CODIGO	DESCRIPCION	
APBA17748	REP.BOMBA EATON 54/64 (990090-000FP)	

CODIGO	DESCRIPCION	
APBA 10130	REP. BBA. HIDRAQUIP (D6NN-E-999-A)	
APBA 14638	REP. BBA. DIR-FORD/NE HOLL (DHPN-3A-674-B)	

CODIGO	DESCRIPCION	
APBA 10130	REP. BOMBA HIDRAULICA CARGADORA (015)	
APBA 10253	REP. BOMBA COMERCIAL P-50 (034)	

CODIGO	DESCRIPCION	
APBA 14562	REP. BBA.DIR.ZF - H60,H80,90J (7673.698.066)	

CODIGO	DESCRIPCION	
APBA 19067	REPARO BBA 90/110PV (RE-164715)	

CODIGO	DESCRIPCION	
APBA 10317	REPARO BOMBA BOSCH (548585)	
APBA 18455	REP. BBA BOSCH - S/RETEN (0548585 S/RET)	
APBA 18455	REP. BBA BOSCH - S/RETEN (L082095.0)	

CODIGO	DESCRIPCION	
APBA 10047	REP. BBA. DIR MF 275 A296 (3175212M1)	
APBA 10088	REPARO BBA. RACINE 1.1/4 (3210703)	
APBA 18455	REP. BBA. BOSCH 159530 - S/RETEN (1361)	

CODIGO	DESCRIPCION	
APBA 10051	REP. BBA.DIR.MF275/290/295/86 (3175458 M91)	
APBA 10066	REP. BBA. HIDR. PRINCIPAL - MF (3176603 M91)	
APBA 10086	REP BBA. RACINE EIXO 7/8" - MF (2730760 M1)	
APBA 10165	REP. BBA. COML. P-30 (0034181-R1)	
APBA 10317	REP. BBA. BOSCH SIMPL - MF 5275/5285/5290	
APBA 10318	REP. BBA. BOSCH SIMPLS-C/RETEN VITON	
APBA 10736	REP. BBA. DIR. CESSNA-WAR MOT (0835606M91)	
APBA 10746	REPARO BBA. DIR. MF-400 (1493867)	
APBA 10768	REP. BBA. DIR. (PLESSLEY) - MF 85X/275A290	
APBA 11591	REP. BBA. VICKERS DE ENGRANAGE (001)	
APBA 12326	REPARO BOMBA BOSCH DUPLA (3603952 M91)	

CODIGO	DESCRIPCION	
APBA 10088	REP. BBA. RACINE 1.1/4 (005)	
APBA 10130	REP. BBA. HIDRAQUIP (61855)	
APBA 10253	REP. BBA. COML. P-50 (RET. BORR) (008)	
APBA 12395	REP. BBA. COML. P-30 (RET.CAUCHO) (007-A)	

CODIGO	DESCRIPCION	
APBA 10130	REP. BBA. HIDRAQUIP (007)	

CODIGO	DESCRIPCION	
APBA 10988	REPARO BOMBA REXROTH (822757)	
APBA 14638	REP. BBA. DIR-FORD/NEW HOLLAND (83910651)	

CODIGO	DESCRIPCION	
APBA 10130	1968.024.0 REP. BBA. HIDRAQUIP (021)	
APBA 10165	REP. BBA. COMERCIAL P-30 (012)	
	REP. BBA. COMERCIAL P-30 (1920.203.8)	
APBA 10253	REP. BOMBA COMERCIAL P-50 (013)	
	REP. BOMBA COM P-50 - BORR. (1920.161.9)	



CODIGO	DESCRIPCION	 Valmet
APBA 11178	REP. BBA. HIDR. MOD VT 65/85/86 (13080-OM)	
